

INTENSIVE SURVEY FORM Historic Preservation Division State Historical Society of Wisconsin

1 City, Village or Town: <i>Sturgeon Bay</i>		County: <i>Door</i>	Surveyor: <i>PHA/Kraviskey</i>	Date: <i>22 Apr. 82</i>	Street <i>North Third</i>
Street Address: <i>110-14 N. Third Avenue</i>			Legal Description:	Acreage:	
Current Name & Use: <i>Apothecary & Open Door Shop/C.J's Shoe Shop</i>		Current Owner: <i>Rodney C. Bohn</i>			
Film Roll No. <i>DR-16</i>		Current Owner's Address: <i>110 N. Third Avenue Sturgeon Bay</i>			
Negative No. <i>-16</i>		Special Features Not Visible In Photographs: <i>Interiors have been modernized</i>			
Facade Orient. <i>W</i>		Interior visited? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			

2 Original Name & Use: <i>Drug Store & Doctor's Office Boot & Shoe Store</i>	Source <i>A</i>	Previous Owners	Dates	Uses	Source	Town
Dates of Construction/Alteration <i>1885-1891</i>	Source <i>A</i>					
Architect and/or Builder: <i>Unknown</i>	Source					

3 Architectural Significance <input type="checkbox"/> Represents work of a master <input type="checkbox"/> Possesses high artistic values <input type="checkbox"/> Represents a type, period, or method of construction <input type="checkbox"/> Is a visual landmark in the area <input checked="" type="checkbox"/> Other: <i>None</i>	4 Historical Significance <input type="checkbox"/> Assoc. with lives of significant persons <input type="checkbox"/> Assoc. with significant historical events <input type="checkbox"/> Assoc. with development of a locality <input type="checkbox"/> Other: <input checked="" type="checkbox"/> None	Section
Architectural Statement: <i>This early, double commercial block has an ornately detailed brick cornice and brick hood-moulds over the second story windows of the Northern Half. The upper story windows and both storefronts have been substantially modified and, for this reason, this large corner building has lost much of its original architectural integrity. It does contribute to the architectural significance of the District, however, in that it is an important corner element of an intact blockface.</i>	Historical Statement: <i>267 Cedar in 1891 (A) The Sanborn Maps show this building as vacant when it first appeared in 1891. (A) This is an indication that it may have just been completed or still under construction.</i>	

5 Sources of Information (Reference to Above) A <i>Sanborn Perris Maps of Sturgeon Bay 1885-1891</i>	6 Representation in Previous Surveys <input type="checkbox"/> HABS <input type="checkbox"/> NAER <input checked="" type="checkbox"/> WIHP <input type="checkbox"/> NRHP <input type="checkbox"/> landmark <input type="checkbox"/> other:	Map Code <i>16-16 3rd/Downtown</i>
B	7 Condition <input type="checkbox"/> excellent <input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> ruins	
C	8 District: <i>Third Avenue/Downtown</i> <input type="checkbox"/> pivotal <input checked="" type="checkbox"/> contributing <input type="checkbox"/> non-contributing initials: _____ date: _____	
D	9 Opinion of National Register Eligibility <input type="checkbox"/> eligible <input checked="" type="checkbox"/> not eligible <input type="checkbox"/> unknown <input type="checkbox"/> national <input type="checkbox"/> state <input type="checkbox"/> local initials: _____	
E		
F		

