

1 City, Village or Town: <i>Sturgeon Bay</i>	County: <i>Door</i>	Surveyor: <i>PHA/Kriviskey</i>	Date: <i>22 Apr. 82</i>	Street North Third Avenue		
Street Address: <i>120-130 North Third Avenue</i>		Legal Description:	Acreage:			
Current Name & Use: <i>Miller's Clothing Store</i>		Current Owner: <i>David G. Miller</i>				
Film Roll No. <i>DR-16</i>		Current Owner's Address: <i>120 N. Third Avenue, Sturgeon Bay</i>		Number 120-130		
Negative No. <i>15</i>		Special Features Not Visible In Photographs:				
Facade Orient. <i>W</i>		Interior visited? <input checked="" type="radio"/> Yes <input type="radio"/> No				
2 Original Name & Use: <i>Commercial Block</i>	Source <i>A</i>	Previous Owners 	Dates <i>1891</i>	Uses <i>Post Office</i>	Source <i>A</i>	Town Range
Dates of Construction / Alteration <i>1885-1891</i>		Source <i>A</i>	"	<i>Meat Market</i>	<i>A</i>	
Architect and/or Builder: <i>Unknown</i>		Source 	"	<i>Drug Store</i>	<i>A</i>	
Architectural Significance <input type="radio"/> Represents work of a master <input type="radio"/> Possesses high artistic values <input type="radio"/> Represents a type, period, or method of construction <input type="radio"/> Is a visual landmark in the area <input checked="" type="radio"/> Other: <i>None</i>		4 Historical Significance <input type="radio"/> Assoc. with lives of significant persons <input type="radio"/> Assoc. with significant historical events <input type="radio"/> Assoc. with development of a locality <input type="radio"/> Other: <input checked="" type="radio"/> None		Section		
Architectural Statement: <i>This large, two-story commercial block appears to have been constructed in two sections- A two-bay section to the North, a three-bay one to the South. While the detailing of both sides are similar the configuration of the large, second level windows varies as does the texture of the brick veneer. The cornice is the same on both sides of the firewall dividing the building sections. The storefronts have, however, been remodeled in a "Colonial" style thus compromising the original architectural integrity of the building, its scale, remaining detailing, and location within an intact blockface (OVER)</i>		Historical Statement: <i>259-261-263 Cedar in 1891 (A)</i>		Map Name <i>Sturgeon Bay-District</i>		
5 Sources of Information (Reference to Above) A <i>Sanborn Perris Maps of Sturgeon Bay 1885-1891</i>		6 Representation in Previous Surveys <input type="radio"/> HABS <input type="radio"/> NAER <input checked="" type="radio"/> WIHP <input type="radio"/> NRHP <input type="radio"/> landmark <input type="radio"/> other:		Map Code 16-15 3rd / Downtown		
B		7 Condition <input type="radio"/> excellent <input checked="" type="radio"/> good <input type="radio"/> fair <input type="radio"/> poor <input type="radio"/> ruins				
C		8 District: <i>Third Avenue/ Downtown</i> <input type="radio"/> pivotal <input checked="" type="radio"/> contributing <input type="radio"/> non-contributing initials: _____ date: <i>22 Apr. 82</i>				
D		9 Opinion of National Register Eligibility <input type="radio"/> eligible <input checked="" type="radio"/> not eligible <input type="radio"/> unknown <input type="radio"/> national <input type="radio"/> state <input type="radio"/> local initials: _____				
E						
F						

Architectural Statement Continued:

do contribute, however, to the architectural significance of the District.

